Design Change Notification

Date: October 24, 2019

Document #: DCN-124 Obsolescence of the MP, HP, and VHP MCR style liquid cylinder models

Subject:

In the spirit of improving liquid cylinder model availability, offering our customers state of the art technology, and best pricing, we will only offer the LCCM regulator versions of our liquid cylinder models starting around 1/1/2020. This will be a running change. As we sell out of the MCR regulator models, our Customer Service Group will facilitate the change to the LCCM versions. The prices of the premium LCCM models will be decreased to the current prices of the MCR versions so there will be no price increase associated with this change.

Background: Chart has traditionally offered the two regulator styles (MCR and LCCM), with the LCCM version being the premium offering. Both regulators operate and perform exactly the same, but the LCCM regulator is easier to remove and install. Thus, the maintenance cost is lower over time. Also, there are fewer potential leak points and fewer replacement parts to stock for repairs.

Products Affected: MCR Models Being Obsoleted

| P/N 10783491 | Dura-Cyl 180MP MCR |
|--------------|-----------------------|
| P/N 10783598 | Dura-Cyl 200MP MCR |
| P/N 10783635 | Dura-Cyl 230MP RB MCR |
| P/N 10810779 | Dura-Cyl 230MP SB MCR |
| P/N 10783539 | Dura-Cyl 180HP MCR |
| P/N 10783619 | Dura-Cyl 200HP MCR |
| P/N 10783651 | Dura-Cyl 230HP RB MCR |
| P/N 10794027 | Dura-Cyl 230HP SB MCR |
| P/N 10840169 | Dura-Cyl 265HP SB MCR |
| P/N 10619771 | Laser-Cyl 200VHP MCR |
| | |


LCCM Models that Replace Them (other than the last one, these have been available for many years)

| P/N 10508764 | Dura-Cyl 180MP LCCM |
|--------------|------------------------|
| P/N 10508772 | Dura-Cyl 200MP LCCM |
| P/N 10602822 | Dura-Cyl 230MP RB LCCM |
| P/N 10496468 | Dura-Cyl 230MP SB LCCM |
| P/N 10496433 | Dura-Cyl 180HP LCCM |
| P/N 10496417 | Dura-Cyl 200HP LCCM |
| P/N 10616546 | Dura-Cyl 230HP RB LCCM |
| P/N 10496492 | Dura-Cyl 230HP SB LCCM |
| P/N 10512561 | Dura-Cyl 265HP SB LCCM |
| P/N 21437026 | Laser-Cyl 200VHP LCCM |
| | |

Also available P/N 10510039 Dura-Cyl 265MP SB LCCM



Description: Following are pictures of both the MCR and LCCM plumbing configurations. Note that the LCCM version requires no copper tubing or associated plumbing components, so the design is much cleaner. Also note that with the MCR configuration there is a separate Rego pressure building (PB) valve. For the LCCM regulator, the PB valve is built into the side of the regulator body.



MCR Style Regulator

LCCM Style Regulator

Chart Parts Note: Chart Parts will continue to stock the Generant MCR style regulators for repairs of your existing liquid cylinder fleet existing as follows:

REGULATOR MCR-MP 125PSI BLUE P/N 20821672 REGULATOR MCR-HP 300PSI ORANGE P/N 20821673 REGULATOR MCR-VHP 450PSI RED P/N 20821674

These regulators will also replace the older style Pentair style regulators that we used on our liquid cylinders for decades.

Contact:

If you have questions or concerns relative to this action, please contact your Chart Customer Service Representative at (800) 400-4683. Thank you for depending on Chart to provide high product quality and service.

